

Do. of R.
Do. of Bri
Do. of Fore
Do. of H
Do. of

Copy

Rpt. 12.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

(When received in London Office.)

Port

Vessel's Name

Port Darwin

No. in Reg. Book

Official No.

Port of Registry (For Foreign Vessels)

Iron or Steel *Steel*

State whether Classed by Lloyd's Register *Yes*

Name of Owners

Date of Verification

14.12.17

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	<i>13</i> ft.	<i>8</i> ins.
From centre of disc to top of statutory deck line at awning or part-awning deck	ft.	ins.
Fresh water line above centre of disc		<i>8</i> ins.
Indian Summer line above centre of disc		<i>6 1/2</i> ins.
Winter line below centre of disc		<i>6 1/2</i> ins.
Winter North Atlantic line below centre of disc		ins.
Distance between the top of statutory deck line on vessel's side and the intersec- tion of the continuation of upper side of wood or iron deck with the vessel's side	at main, spar or upper <i>skeller's</i> dk.	<i>1 5/8</i> ins.
	at awning or pt.-awning dk.	ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

Sd J. Mc Lvenna Surveyor.

(To be filled up in London Office.)

Statement No. *23995* Date of Committee's Minute

6.11.17

Particulars for Record in Register Book.	Moulded Depth	<i>43</i> ft.	<i>8</i> ins.
	Freeboard	<i>13</i> ft.	<i>8</i> ins.
	Corresponding Draught	<i>30</i> ft.	<i>8</i> ins.


Freeboards compared and found correct by _____ date

Is fee paid? _____ Form for Certificate

Instructions _____ date

Certificate written _____ Noted for posting

comparatory freeboards a condition of classification.



©2020

Lloyd's Register Foundation