

1500.10.17

1

Bangloe Bethlehem

Sent to Chief Surveyors 25-1-18

Received from Chief Surveyors

VESSEL'S NAME Ste % Ardgoil Report Cluk No. 17237

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

1st entry

When due

+ 100 AI (Steel)

2 D^{ks} (Ste) + web frames.

"Longitudinal framing".

"Carrying fuel oil 2P above 150° 2 in 10B + 10T. (Col 5)

"Tween 10th Bst in after hold dispensed with. 5 Bst to Upper d^{ks},1 Bst to Second 10th only."

Cells 10B a 120' x E 21' f 176'. 1093t. DT 36. 958t. APT 39t.

FK. Cem. Lloyd's A+CP. P36. B120' F44.

M

MEI.

26-1-18

The Surveyor should be requested to forward a sketch showing details in the fore peak when forwarding the 1st entry report on the sister vessel now building.

MEI.



© 2020

Lloyd's Register
Foundation

W1028-0013

W1028-0016