

Chief Surveyors

Received from Chief Surveyors

SHIP'S NAME Stl T.S. MANCINIUM Report GRK No. 19822

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey 1st Entry When due

✠ 100 A.I. (Steel). With keelboard. "Sludge vessel"
10" (Stl), 2nd D^k (Stl). Web frames forward of E+B spaces.
D.T. f 33' 135t, F.P.T. 33t, A.P.T. 38t.
F.K, 5 B.H, pt ceme, Cnysd A.C.P.
F 56'
machy aft.

S.R.V

{ Bottom of vessel clear of E, B spaces to specially examine in drydock.



© 2019

Lloyd's Register Foundation

16.3.33

W103-0225

LONDON.