

ESHEET AKE RPD D. doublet	Thick- ness	Port.	Std.	Port.	Std.	Thick- ness	Port.	Std.	Port.	Std.	Thick- ness	Port.	Std.	Port.	Std.	30
---------------------------------	----------------	-------	------	-------	------	----------------	-------	------	-------	------	----------------	-------	------	-------	------	----

"CRANLEY"

Vessel laid up.

Vessel examined for hull Special Survey and
specification based on recommendation made,
completed by Messrs. J. H. MacIlwaine & Son.

Copy in office.

Awaiting decision of Owners whether to carry
out survey repairs or scrap vessel.

First Entry Report and plans, shell drillings,
etc. handed over.

J. H. MacIlwaine
30-1-50



© 2020

Lloyd's Register
Foundation

to remain as classed in the Register Book without fresh record of survey, to remain as classed
survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel has been prepared and examined as detailed above