

No. of Bilge Injections *one* sizes *7* Connected to condenser, or to circulating pump *Correct*. Is a separate Donkey Suction fitted in Engine room *yes*  
 Are all the bilge suction pipes fitted with roses *yes* ✓ Are the roses in Engine room always accessible *yes*  
 Are all connections with the sea direct on the skin of the ship *yes* ✓ Are they Valves or Cocks *valves except 6*

*P.S. "Stal"*

*Cpn. 6236.*

*Shn. 2048.*

*It is submitted that  
 this vessel is eligible for  
 THE RECORD.*

*L.M.C. - 10.21.*


*F.D.*

*Ans*

*23/11/21.*

*The Copenhagen Surveyors should be  
 requested to state whether the screw  
 shaft is fitted with a continuous liner  
 or otherwise.*

*Ln 16/12/21*



© 2020

Lloyd's Register  
 Foundation

thickness of girder at centre *8 3/8" x 3/8" x 2*. Length as per rule *25 7/8"* ✓ Distance apart *9 1/2"* Number and pitch of stays  
 Working pressure by rules *206 lbs.* Steam dome: description of joint to shell *✓* % of strength of joint *✓*  
 Thickness of shell plates *✓* Material *✓* Description of longitudinal joint *✓* Diameter of rivet holes *✓*

*32'-4" ft*

*given as*

*tion,*

*Water Capacity.*

*Tons.  
 51  
 65*

*29/10, 16/11,  
 9/9, 9/9*

*29*