

Do. of excess of Hatchways 18.52
 Do above Crown of 39.20
 Engine Room 1888.57
 Gross Tonnage 217.29

Girth of Half Midship Frame (as per Rule) 34.73
 1st Number 72.93

When built 1901
 By whom built The Strand
 Launched

Wire

W1054-0208

Chief Surveyors 18. 7. 01

Received from Chief Surveyors

L'S NAME See. S.S. "Gratia"

Report See No.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.)—Extract from Sub-Committee's Report, 24/5/32.)

of Survey Equipment

When due

It is submitted that before this case receives the consideration of the Committee the Sunderland Surveyors should be requested by wire to send full particulars of the equipment and the equipment number for the information of the Committee.

Let. to No. 1877/01.

C. K. P.
 18/7/01

In 'tween Decks, Size and Spacing	Centre-line BHD	Centre-line BHD
" Hold	fore & aft in hold	bulkhead
Quarter, 'tween Dks.,	'tween Dks. as per approved plan	
" in Hold		

" Tie Plates
 " Deck, Material and thickness IRON
 Forecastle Deck Stringer Plate, brdth & thcknss
 " Angle on ditto

3 1/2 13
 16 1/2 10
 3 7
 2 10
 14 9
 7/20
 7/16



© 2020

Lloyd's Register
 Foundation