

Is the ballast pump fitted with a direct suction from the engine room bilges *yes* ✓ State size *6*
connected to the cooling water pumps *5" each* ✓

3475
No. *NORDBO.*

Cpn. Rept. 6698.

*It is submitted that
this vessel is eligible for
THE RECORD. + LMC. 1123.*

C.L.

*OIL ENGINES. 45C. S.A.
12cy 23 $\frac{1}{4}$ " - 35 $\frac{7}{16}$ " 482 NHP.
D.B 100 H.*

ART. BURMETSTER & WAIN, CPN.

J.A.

2/12/23.

2020
Lloyd's Register
Foundation

W1058-0176

33 inner surfaces Steam pipes are fitted from the donkey boiler to enable the high pressure air receivers to be cleaned internally by means of steam and caustic soda. ✓ Is there a drain arrangement fitted at the lowest part of