

1m, 10, 11

1 E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME

Pat Jackson

REPORT

Vol. No 16

No.

3553

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

oil Engines 4 S.C.S.A. S.R. gland.

to 1 Se. Shaft.

7 Cy. 12 1/2" - 15"

~~If Boilers fitted with forced draught~~

Tail Shaft.

If fitted with a continuous liner

no

If fitted with an outside gland of

approved type

Yes.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ Linc. 642

Note for S.R. Spare cylinder valves to be placed on board. (Advise owners)

S.R.

9.7.42

cluded.)

Capacity.

Tons.

3

16.5

36

Ma

Aug



© 2020

Lloyd's Register
W1064-0010
Foundation