


to forward-slush well. The 2" to main hold. The 2" to spare buster.

No. of Bilge Injections 1 since $3\frac{1}{2}$ " Commented to condenser or to circulation pump. To separate bilge from engine room fittings

Hull 26621

Submitted the Hull Surveyors be requested to state the length of the stern bush this information having been omitted from their report.

T. J. S.
16.8.13.



© 2020

Lloyd's Register
Foundation

W1069-0024

Smallest distance between bottom of upturned hull and bottom of

Thickness $1\frac{5}{32}$ " Range of tensile strength 29 tons. Are the shell plates welded or flanged ✓ Descrip. of