

For the information of Surveyors and the Committee only.

Received at \_\_\_\_\_ Office \_\_\_\_\_ 19\_\_

# Lloyd's Register of Shipping.

(Report on Vessel No. \_\_\_\_\_ Port \_\_\_\_\_)

No. **4458-59.** SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~  
Castings, manufactured by **Messrs. A.-B. Bofors**  
of **Bofors** for the Vessel No. **"VIRGILIO"** being built  
by \_\_\_\_\_ of \_\_\_\_\_  
have been inspected by me as set forth below and found to be, so far as can  
be seen, **sound and free from defects.**

Work on ~~Forgings or~~ Castings.

Lloyd's

**Gothenburg, 15th March, 1927,**

No. **4458-59.**

LR GA 4.3.27.

**1 Welin davit frame. 1 Welin davit arm.**

	STERN FRAME.	RUDDER FRAME.	STEM.
Material* ...	<b>S.M. Steel.</b>	<b>S.M. Steel.</b>	
made ...	<b>Casted.</b>	<b>Casted.</b>	
annealed ...	<b>Yes.</b>	<b>Yes.</b>	
tensions ...	<b>---</b>	<b>---</b>	
progress on inspection ...	<b>Finished.</b>	<b>Finished.</b>	
when Inspected ...	<b>4.3.27.</b>	<b>4.3.27.</b>	
CASTINGS.			
tests on Standard Test Pieces.			
tile Test—			
Pounds per square inch ...	<b>48.0</b>	<b>45.3</b>	
Extension per cent. ...	<b>28.8</b>	<b>35.4</b>	
Bending Test—			
Angle before fracture ...	<b>120° good.</b>	<b>120° good.</b>	
Drop Test—			
Height from ground ...	<b>---</b>	<b>---</b>	
hammering Test—			
If made according to Rules and found satisfactory ...	<b>Good.</b>	<b>Good.</b>	

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.


Fee (if any chargeable) £ **---** :

To be paid at **GOTHENBURG.**

\* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

an. 128. T.

© 2020



Lloyd's Register  
Foundation

Seamless, lap welded or riveted longitudinal joint.

**RIVETED**

Material

**STEEL**

Range of tensile strength

**44/50.5 Kgs.**

Working p