

F.E.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *St. S. M/V "ACCLIVITY"* Rpt. *Grk* No. *19370*

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

long

Transverse No. *1722*

Depth "d"

Table No.

Description *angle frames as approved*

Longitudinal No. *5740*

Proportions $\frac{\text{Length}}{\text{Depth}} =$ *15.6*

Deck Sheerstrake *as approved*

This vessel appears to have been built in accordance with the plans and the approved plans, and it is submitted she is eligible to be classed

100 A. 1. (Steel). Carrying Petroleum in Bulk

1 D* (Stb).

Cell D.B. 74' 123t, D.T.a 5' 46t, F.P.T. 38t, A.P.T. 16t

F.K, 9 B.H, pt Cem, Planks A CP.

P 43' TRUNK 101', F 20'.

machinery aft.

await mach



© 2020 Lloyd's Register Foundation
21.11.31

W1071-0049