

W1078-0289

F.E.

Ship Surveyor

Received from Chief Ship Surveyor

NAME *Steel S.S. PORT LAURIE* Rpt. *Low* No. *84137*

is of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee Report, 24/5/82.)

Case No. *40-8*

Depth "d" *14.83*

Table No. *3*

Description *Single Angle as approved*

Serial No. *7233*

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.25}{1}$

Deck Sheerstrake *as approved*

This vessel appears to have been built in accordance with the approved plans, and it is submitted she is eligible to be classed

ed \times 100.A-1. (Steel) as recommended
1 DK (Steel) well DK ✓


Cell DB f103' 172t, FPT 85t. APT 35t

FK, 3BK, Cam, Plyd 1v CP, Q114' F23' Melby Aff.

Date of build 1/21

22.3.21

check the numbers of hatch webs and fire and afters are as
but the Surveyor's should state if this is so and also whether the



Lloyd's Register
Foundation