

1

Sent to Chief Surveyors 21.7.17

Received from Chief Surveyors

VESSEL'S NAME *Shells Nairana*

Report *ES*

No. 37135

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_ When due \_\_\_\_\_

100 A-1. Steel / Shelter DX with freeboard  
2 DX (one pl steel ws) + Shelter Deck (Steel Tanks)  
C 100 B 13' 48" A E f 98' 1436 F.P.T. 386 A.P.T. 596  
FK + BK 2. SBH. pl asp. Lugs are P. F 60'

*M*  
21.9.17



© 2020

Lloyd's Register Foundation

W081-0342

W1081-0343

ckness 18x2

Angles on ditto. FRIEZE PLATE