

Lloyd's Register of Shipping.

(Report on Vessel No. _____)

Port Middlesbrough

No. _____ SHIP ~~FORGINGS OR~~ CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~ Castings, manufactured by Wm E. Jopling & Son Ltd of Sunderland for the Vessel No. 546, being built by Ropner & Son of Stockton on Tees have been inspected by me as set forth below and found to be, so far as can be seen, Sound

Crosshead for steering gear being constructed by
Moore Pipe & Eng & L^{td}

Mark on Forgings or Castings.

Lloyd's

No. 4440



5-6-24

D. D. Williamson

Crosshead Sunderland

STERN FRAME.

~~RUDDER FRAME~~

STEM.

Material* ...

How made ...

Dimensions ...

Progress on Inspection ...

Date when Inspected

Hammering & Heating
5-6-24

CASTINGS.

Tests on Standard Test Pieces.

Tensile Test—

Tons per square inch

29.0

Extension per cent. 2.7

30.0

Cold Bending Test—

Angle before fracture

120°

Drop Test—

Height from ground ...

Hammering Test—

If made according to Rules and found satisfactory ...

Yes

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

dfB

Fee (if any chargeable) £

To be paid at



© 2020

Lloyd's Register Foundation

* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

RECEIVED
MAY 30 1924
LOYD'S REGISTER

Means The Register Ship Co

No 546

Crashend

S/S. Anakepool

Mdb report N^o 12167

Suggested card have special

note :-

"Correspondence re sinking
retained."

8/8/62
L.S.



© 2020

Lloyd's Register
Foundation