

Alga

N. N. "KAUPO"

F.E.

Received by Chief Ship Surveyor 15. 12. 05

Received from Chief Ship Surveyor

VESSEL'S NAME *Sea S.S. "Alga"* Rpt. No. *49808*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>3/20"</i>	<i>Proportions & in lieu of doubling.</i>
Spar Sheerstrake . .		
Description of Framing:— <i>Deep (Bulb-angle) framing.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed † 100 A 1 ("Steel") as recommended.

† 100 A 1 ("Steel")

1 DR (pt Sm & pt St) & deep framing.

M. B = Cell DBa 100' x E 20' f 138' 725E APT 706

FK 58H Cam. Lloyd's A4CP P28' B92' F29'



© 2020 15/12/05

Lloyd's Register Foundation

W1086-0225

PILLARS, In 'tween Decks, Size and Spacing	Deck, Material and thickness
" Hold	Forecastle Deck Stringer Plate, brdth & thckns
" Quarter, 'tween Dks.	Angle on ditto

4 1/2" x 1 1/2" @ 48"