




JANKO



LINE OF FRACTURE OF BOTTOM SHELL.



PLAN OF UPPER AND MIDDLE STRINGERS.



DETAIL OF WRINKLES ON STRINGERS.