

4

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

S NAME *St. Se* *BARCELONA*

Rpt. *Bel*

No. *2720*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey

COMPLETION OF *2nd* S.S. No. *1* *dealt with at owner's convenience*

The *2nd* S.S. No. *1* partly held at *Barcelona*

completed, and the following repairs done (due to *blast*):-

Repairs & renewals effected to decks, tank top plating, floors, hatches etc as considered necessary & minor repairs effected.

It is submitted the vessel is worthy to remain as classed, with record

Survey *9.26* and notation of *S.S. Bel M1-25* ~~as recommended.~~
Subject as above.

100 A.I. Spas (Ks)
9.26 Bel.
S.S. Bel M1-25 } *subject etc*



© 2020

Lloyd's Register
Foundation
W1094-0074

28.9.26