

Steamer "BARCELONA"

and tank top plating shipped and painted, transverse tie plate.

in way of forward bulkhead removed.

Watertight doors examined.

No. 3 hatchway coaming plate, in way of deck steam pipe.

double.

Engine room casings and skylights repaired. 4 deck plates

in way of same renewed.

Stripped plate of yamane's deck, in way of the saloon.

port side, out and part removed.

Freeboard verified.

C. H. Fowling

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

[illegible]

* When a hawser anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd hawser

CHAIN CABLES

[illegible]

13.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much heated as to prevent the ink, or to cause it to show through to the other side.

General Committee
Thursday, 1st September, 1927
Chairing Committee's

decision conference



© 2020

Lloyd's Register
Foundation