

1

Sent to Chief Surveyors 23. 4. 08

Received from Chief Surveyors

VESSEL'S NAME *St. L. L. "Barcelona"*

Report *Sts.*

No. 26478

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

First entry

When due

+ 100 A 1 ("Steel") *Spar Deck*:

2 Dr (M set) + Spar Dr (St-ns). Orlop beams in No 1 hold.

W. B = Cell DB a 114' u E + B 62' f 170' 877t FPT 100t APT 34t

FK 7BH Cam. Lloyd A+CP P66' F58'

C. H. J.
23/4/08



© 2020

Lloyd's Register
Foundation
W1094-2079

Quarter, 'tween Dks., " " in Hold

Deck. Material and thickness

* If Iron or Steel Deck, state if whole or part, and if wood