

Do. above Crown of
Engine Room
Gross Tonnage

Longitudinal Number

12923

Owners Keith Hull & Hambur

8.17.

Received by Chief Ship Surveyor 9. 11. 17

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. S.S. "MECKLENBURG"

Rpt. Nwc. No. 70403

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor

by return It is submitted the Newcastle Surveyors be requested to state whether cargo battens are fitted in the shelter deck 'tween decks.

Lr. Nwc. 9/11/17.

[Signature]

9. 11. 17



© 2020

Lloyd's Register
Foundation

W1094-0101

2nd 11.16

BEAMS, Third and Fourth Deck, Single Angle,
Bulb Angle, Plate, Tee Bulb, or Channel
Angles on upper edge

Angle on ditto