

2m, 10, 23. H.

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "HOUTHANDEL".

Report Ant.

No. 14727.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/5/82.)

No. 7 SURVEY PARTLY HELD.

When due 10.75 When proposed to be completed

Portion of Survey held, &c.,

To complete the survey the following remains to be done: - holds, peaks, chain locker, lower bunkers, engine and boiler spaces, decks, anchors, cables, windlass, steering gear, pumps, watertight doors, hatches and ventilators to be examined, all tanks to be tested and the freeboard to be verified.

A bower anchor, stream wire and towline require to be supplied, lifeboats and main stay to be renewed, main topmast to be rewedged and repairs are required to steering gear blocks, hatch web slides, fidley casing and pipe casings in bridge bunkers.

15. 3. 27.



© 2020

Lloyd's Register
Foundation

W1096-0216