

2m,7.42.

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "BRETWALDA" REPORT Grk. No. 22064

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~


(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Damage ~~When due~~

Subject to (a bower anchor and 30 fathoms
of chain cable being supplied the collective weight
of the anchors to be brought up to Rule requirements).

('Extension of Bulkheads' partly complied with.)

NWC. 100805



©

was 19
23.11.42

Lloyd's Register
Foundation

W11-0067

Reverse Frames.....

Longitudinals.....

Transverses.....

Have Sluice Valves been examined and found

Caulking.....

Treenails.....

Anchors, No. of.....

Cables (State if any).....