

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

Bn. 13658-13695

SEL'S NAME

BEGERIN

Rpt.

Hull

48037

Jussodaf

No. 174

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Oil Engines 4 S.C.S.A

6 cy. 11" - 17 1/16"

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner

no

If fitted with an outside gland of

approved type

ye

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + Linc. 7.37

Jmm

3.7.37



© 2019

Lloyd's Register
Foundation

WH-0136

AIR RECEIVERS:—Is each receiver, which can be removed,

Is a drain fitted at the lowest part of each receiver