

1

Din COT

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl Se Lug " 79 B " Report Gls No. 46064**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry

When due _____

✱ A.I. (Steel) " for towing services Rio Negro, Limay to Hauguen".
1 D" leak.

F.K., H.B.H., Cloyds A. & C^o.

RETAIN



© 2020

Lloyd's Register
Foundation

W1101-0132

Spacing.....

" " " Through Plate or
Intercoastal Plate...
" " " Foundation Plate on