

REPORT of SURVEY for REPAIRS, &c.

Survey held at Trieste & Anafalcone Date, First Survey June 17 Last Survey July 19 1924

On the Wood, Iron or Steel "PROMONTURE" (VILLE DE BELFORT) Master

TONNAGE: Gross 998.34 Net 886.7

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Contemplated

Was a damage report made by anyone else? If so, by whom?

IRS, OR EXAMINATION AS PER RULE, FOR Advancement of Survey for Classification (see Bordeaux Reg 3372)

done: Vessel placed in dry dock, bottom and rudder cleaned, examined and rescaled.

Bunkers and holds cleared, ceiling lifted, all exposed steel work examined, sealed & rescaled.

Repairs for wear & tear: 1st hose pipe renewed; casing in side bunkers repaired

Table with 9 columns: Plates, Frames, R. Frames, Floors, Beams, Str. Plates, Dk. Plates, Other Items, and a summary row.

Table with 3 columns: Condition of Decks, Condition of Hull, and Condition of Machinery.

General Observations, Opinion as to Class, Recommendation, &c.:-

This vessel is, in our opinion, worthy to be classed in the Register Book with

Record of Survey 7.24 and Notation 55. Tri 123 - 7.24, when the classification survey has been completed.

Committee's Minute MAY 1 1925

Bardeaux Rep. N^o 3372 is enclosed herewith.

Em.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

Number of Certificate.	Anchors. #	WEIGHT, EX STOCK.			WEIGHT OF STOCK.			TEST, PER CERTIFICATE.				WEIGHT REQUIRED BY TABLE 30 or 31.			Description of Anchor.	Makers.	Where and when Superintendent
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons.	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collective Weight.																
	Stream																
	Kedge																

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]