

VESSEL'S NAME **WATER SAIL SCHONE SAVVA**


Report **Fiwime**

No. **2852**

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in $\frac{9}{20}$ th of an inch.

STRAKE.	AMIDSHIP.				FORWARD.				AFT.				REMARKS.
	Original Thickness.	Thickness by drilling.		Diminution if any.	Original Thickness.	Thickness by drilling.		Diminution if any.	Original Thickness.	Thickness by drilling.		Diminution if any.	
		Port.	Std.			Port.	Std.			Port.	Std.		
DECK STRAKE													
Below													
DECK STRAKE	E	6	66	- -	6	66	- -	6	66	- -	✓		
Below	D	5	55	- -	5	55	- -	5	55	- -	✓		
"	C	5	55	- -	5	55	- -	5	55	- -	✓		
"	B	5	55	- -	5	55	- -	5	55	- -	✓		
"	A	6	66	- -	6	66	- -	6	66	- -	✓		
"													
"													
"													
"													

Inspected 2020

 Lloyd's Register
 Foundation

Drillings at ends to be made in the vicinity of the peak bulkheads.

W1108-2140