

Length as per Section 30 243 0 Extreme Breadth Outside... 44 0 Depth of Hold 19 2 1/2 No. of Decks with Flat laid 2
 Length of Keel... 329 7 1/2 Round of Beam... 7 Depth from limber-strakes to under side of lower deck beam 8 10 1/2 No. of Tiers of Beams Two

to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME WOOD S. "FOREST PRIDE" Report Sea No. 897

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.)—Extract from Sub-Committee's Report, 24/5/02.)

ature of Survey

When due

The materials used have been treated with Carbolineum

12 A.1. "salted"

1 Dk. 2 hrs beams.

"Specially treated."

A4C.P. P 39, F 59.

Subject to a Special Survey equal to a half time Survey at four and eight years.

M a.e.s.
7-1-20

It is concluded, the sizes of deck and hold beams are as approved and that bedding knees have been fitted to hold beams as shown on approved plans, but the Surveyors should be requested to state if this is so.

Deck Beams

4-1 1/8" " " waterway, beam & knee ✓ (drifted) S

2-1 1/4" " " " clamp & knee " B.

2-1 1/4" " " " & ceiling " S



© 2021

Lloyd's Register Foundation