

total capacity of the vessel, and the inside of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Steel Screw Ketch "ARLADNE"; No. 06687 in the Register Book;  
225 tons gross; Built in 1906 - 11 mo.; Port - Grimsby;

Classed: \* 100A1  
Steam Trawler  
9,28.  
S.S. No. 3-2,19  
S.S. No. 1-28.

\* LMC 9,28  
TS 9,28.

Steel Screw Ketch "AURORA"; No. 06751 in the Register Book;  
225 tons gross; Built in 1906 - 10 mo.; Port - Grimsby;

Classed: \* 100A1  
Steam Trawler  
8,28  
S.S. No. 3-2,19  
S.S. No. 2-28.

\* LMC 8,28  
TS 8,28.

Owner: Charles Dobson

These trawlers became due for Annual Boiler Survey in September and August last, respectively, but, in a letter, dated 6th instant, the Owner states he has decided to withdraw them from the Society's Classification.

In the circumstances the Classing Committee, who had the cases before them on Tuesday, 12th instant, decided to give instructions for the character of each vessel to be withdrawn from the Society's Register Book and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owner's request.

14th November, 1929.

RETAIN



© 2021

Lloyd's Register  
Foundation

Char. or Assigned

Wille 0143

Wille 0149