

total capacity tons. 111 tons, 111 tons, 111 feet tons.)
N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 165-16 Port Ant.

CHARACTER.
X for Special Survey.
Date of last Survey and of Periodical Surveys.

+100 A.1.
Stm Trawler 1228
S.S. Ost. Nos. -624

28.

LLOYD'S REGISTER OF SHIPPING

14, RUE DE LA TOUR-NOTRE-DAME, 14

A. COUTURE
LLOYD'S SURVEYOR

TEL. 10.80

Référence

S



BOULOGNE-SUR-MER, LE 1st. of March 19 30

Lo. 10/4/30

Dear Sir,

Answering to your letter of the 25th. of March concerning the classification of the Trawler "JEAN DORE" to the Bureau Veritas, I beg to send you the letter, which I received to-day, from the Owners.

I am Dear Sir,

Yours faithfully

Alouche

To the Secretary of the Lloyd's Register

LONDON

Bl due 9.29

assigned) as
now verified

er, or Y.M. of W
state of on Pett
Then put on, Mont


s, Yards, &c.....
ition, how ascerta
ate if wedges

ment letter
ors, No. of
s (State if now r

length.....
(on board)
Rule length.....

ser & Warps
ding and Running

the Register Bo
as classed and



© 2020

Lloyd's Register
Foundation

W1120-0006

10m1028.
requested not to write

| | | | |
|--|---|---|-----------------|
| Special Damage or Repair Fee (if any)£ | : | : | 19 |
| (per Sec. 29) | : | : | |
| Travelling Expenses (if chargeable)£ | : | : | Received by me, |
| | : | : | 19 |
| Second Surveyor's Fee (if any)£ | : | : | |

Surveyor to Lloyd's Register of
General Committee

