

should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

From The Norwegian Shipping  
and Trade Mission,  
144, Leadenhall Street,  
LONDON, E.C.3.

WOKINGHAM COPY.

5th February 1942.

The Secretary,  
Lloyd's Register of Shipping,  
WOKINGHAM.

Dear Sir,

s.s. "BJORNVIK".

In reply to your letter of the 23rd ultimo,  
reference H. & F., in regard to the General Examination  
and Freeboard Surveys now due, we regret to advise you  
that this vessel has since been lost.

Yours faithfully,

THE NORWEGIAN SHIPPING & TRADE MISSION.

*Bango ballens*  
Society's Freeboard (if assigned  
painted on Ship and now veri



© 2021

Lloyd's Register  
Foundation

W4120-0122

longitudinals.....	Have Sluice Valves now been examined and found efficient /	Breasthocks & Sterns..... ditto	Copper, or Y.M. (State if on When put on,
transverses.....		Transoms, Pointers, & Crutches ditto.....	Boats .....
keels.....	Have Watertight Doors now been examined and found efficient /	Timbers of Frame at openings ditto.....	Masts, Yards, & .....
girders.....		Ditto Ditto at other places ditto.....	Condition, how as (State if recd
			Sails .....
			Equipment, letter
			Anchors, No. of .....
			Chain Locker .....
			Cables (State if .....
			length..... (on board
			Rule length