

(2m.11.5.)

1.

Sent to Chief Surveyors 23.4.07

Received from Chief Surveyors

VESSEL'S NAME *Ste. S.S. "Makambo"*

Report *Luk.* No. 15026

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*Final entry*

When due


† 100 A 1 ("Steel")

*1 DR & deep framing. Well back.*

*N. B = Cell DB a 35' x E 15' f 109' 211E APT 29E*

*BK 8" 4BH Cam. Dwyph A & CP P & B 135' F 27'*

*C. H. P.*  
*23/4/07*



© 2020

Lloyd's Register  
Foundation

W1127-0136