

## FREEBOARD VERIFICATION FORM FOR STEAMERS.

to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME STEEL S.S. "WINONA COUNTY" Report N.Yk. No. 17480.

## For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Date of Survey

When due

The Downton Pump has been dispensed with for the present.  
Chain Cables are of Cast Steel, tested as required.

✗ 100 A.1. (steel) "Shelter Dk. with Freeboard"

1 Dk. (steel) and "Shelter Dk. (steel); and Webframes. Longitudinal Framing.

Cell DB 331' 1512t. FPT 187t. APT 175t.

FK. 7BH to Shelter Dk. ft.cem. A9C.P

P45', B 110', F 38' on Shelter Dk.

Carrying oil fuel F.P. above 150°F in D.B. & Peak Tanks.

M. AEB  
10-11-19

The Surveyors should be requested to state if Oil Fuel is being carried as cargo in Double Bottom & Peaks.

yes.  
on 18/2/20.



© 2019

Lloyd's Register  
Foundation

W 1129-0015