









GENERAL REMARKS—(continued).

Rpt. 4.

REPO

Date of writing Report

No. Survey h  
Reg. Book.  
on the

Built at Queen

Engines made at

Boilers made at

Registered Horse

Nom. Horse Pow

ENGINES

PARTICULARS FOR RECORD in the REGISTER BOOK.—Length of Poop ☒ ft., R.Q.D. 79.25 ft., Bridge 8.75 ft., Forecastle 22.5 ft.  
(in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated ☒

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given should appear in the Register Book) 1 or (see)

Official No. 146387; Signal Letters ☒

State if Machinery is fitted aft Yes

How are the surfaces preserved from oxidation? Inside Paint and Cement

Outside Paint

PARTICULARS OF WATER BALLAST.—State whether the Double bottom is constructed on the cellular system or with girders on floors No DB.

Where Fitted.	Length.	Water Capacity.	Where Fitted.	Length.	Water Capacity.
	Feet.	Tons.		Feet.	Tons.
Double bottom, aft,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Fore peak tank,	<u>20.2</u>	<u>45</u>
Double bottom, under Engines and Boilers,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	After peak tank,	<u>14.75</u>	<u>34</u>
Double bottom, if under Engines only,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Deep tank, aft,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Double bottom, if under Boilers only,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Deep tank, forward,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Double bottom, forward,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Other tanks, if fitted,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Total capacity of double bottom		<input checked="" type="checkbox"/>	(If necessary, furnish further information by sketch.)		

\* The wells are not to be included in the lengths of the tanks.

State whether the above have been tested as required by the Rules Yes

Order for Special Survey No. 1161

Date 2/10/20

No. 463 in builder's yard.

Dates of Surveys held while building

1920. Aug 30. Oct 22. Nov 8. 29. Dec 17. 21. 1921. Jan 12. 13. 24. Feb 1. 14. 17. 23. Mar 2. 4. 11. 17. Apr 5. 8. 19. 20. 25. May 3. 5. 6. 31. June 7. 14. 19. 25. July 6. 19. Aug 25. Sept 1. 12. 19. 29. Oct 11. 14. Nov 18. 25. 29. Dec 1. 8. 21. 1922. Jan 19. 1923. Aug 31. Sep 10. Dec 11. 30. Nov 20.

Total No. of Visits 49

Surveyor's Signature

Geo. L. Lyle

© 2021

Lloyd's Register Foundation