

After peak tank examined, also tested.  
Their cables covered 300 fathoms 2-7/16" on board. ✓

*sent to* ✓

Extract from N.Yr. S.O. letter dated 20.7.42.  
Original with "S"

S/S "GULFPENN" N. Yr. 41811. The Philadelphia Surveyors advise that the crankshaft journals were not examined when the vessel was under survey in June, 1941, and your proposal to let the notation of ~~7~~ LMC 6\_41" be made subject to these journals being examined at the earliest opportunity is concurred in.



© 2020

Lloyd's Register  
Foundation

W1133-0004

*Handwritten initials/signature*



© 2020

Lloyd's Register  
Foundation

... obbligation is concluded in.  
... employe ce space l'omluere peice examinee se the  
... l'achetei ce ref the notation of ...  
... upon the l'essai was under ...  
... egalite quee the clarkent's l'omluere sece hoc  
... CARTE de M. LA. 17811. -pe EMJ...  
... M. J. L. 2. O. Joffe de 30. A. 45.  
... M. J. L. 2. O. Joffe de 30. A. 45.