

FREEBOARD VERIFICATION FORM FOR STEAMERS.

When received in London Office

31- 8- 21

Surveyors

Received from Chief Surveyors

NAME *Steel S.S. "AGWIHAKRE"*

Report

Ph

No. *4231*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/02.)

Survey

When due

* 100. A.I. (Steel) "Shelter Dk with freeboard"

Cumpring petroleum in bulk

DK (Steel) & Shelter Dk (Steel) & Webframes, longitudinal framing

all I/B & E/B 89' f 40' 448t, FPT 186t, APT 84t

DK, 18BH (9 to Shelter Dk, 9 to Upper Dk.) ft Cen, A & CR.

F 44' on Shelter Dk, Mchly App.

M

Ph

21.9.21.

inquires on Light Vessel "Cerro Azul" regarding arrangements at ends.

S.O. 29/9/21



© 2020

Lloyd's Register
Foundation
W1133-0621

Freeboards compared and found correct by

Date

fee paid?

Form for Certificate