

W. S. 141

F.E.

Received by Chief Ship Surveyor 13.9.34.

Received from Chief Ship Surveyor

VESSEL'S NAME S.T. S.C. "WAIWERA" Rpt. Bel No. 11,351

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

1st Long. Transverse No. 22145

Depth "d"

Framing: Table No. ✓

Description Channel frames & reverse

2nd Longitudinal No. 58195

frames as approved

Proportions Length = 11.87  
Depth =

Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **✠ 100 A. 1** "with freeboard," as recommended. The Summer freeboard of *See verification form* from centre of disc to top of ~~statutory~~ deck line at *See verification form* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification. 2 Dks & Shelter Dk, 4th Dk in no. 3 hold.

Cell DB 431'2438t, FPT 122t, APT 171t.

FK, 8 BH (Coll BH to Shelter Dk 7BH to 2nd Dk), pt cem, Lloyd's A & CP.

B. 196', F. 65'

