

1

W1134-0113

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stal S.S. "PHILOMEL"*

Report

*gls*No. *41488***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

When due

*See Separate endorsement regarding date of build.*** 100-A-1. (Stal) Shelter Deck with freeboard ~**1 Dk (Stal) v Shelter Dk (Stal ws) 2nd Dk in No 1 Hold**Cell Dk 236' 357t, FPT 16t, APT 18t**FK, 3BK to Shelter Dk, 2BK to upper Dk, Cmn, Ply do A.C.**Date of build 11.21**1373' on Shelter Dk*

© 2020

18-11-21

Lloyd's Register
Foundation