

F.E.

ved by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SEL'S NAME Stl T.S.M.V. "ROMOLO" Rpt. Iv No. 7375

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long

Transverse No. 16936

Depth "d" _____

Framing: Table No. ✓

Description Bult angle - channel frame

Longitudinal No. 46990

as approved

Proportions $\frac{\text{Length}}{\text{Depth}} =$ 13.87

~~Deck~~ Sheerstrake

as approved

Revised Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A. 1. (Steel).

2 Dk (Stl), 3rd Dk (Stl) in No 1, 2, 3 Holds

Cell D.B. 426' 16975, F.P.T. 2275, A.P.T. 1845.

F.K, 8 B.H, pt Cem, Lloyds A.C.P.

P 31', B 214', F 47'.

[Handwritten signature]

[Handwritten signature]
21.12.26



© 2020

Lloyd's Register
Foundation

W1138-001