

5m. 7.30.

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME

*St. Lc. "THE SULTAN."*

Report

*Gls*

No. *52030.*

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/6/93.)

Nature of Survey

*1<sup>st</sup> Entry.*

When due

*Revised Rules.*

✠ 100 A1 (Steel).

1 Dk (Std) Well Dk.

Cell D.B. 123' 174t, F.P.T. 56t, A.P.T. 22t.

F.K, 3B.H, Cem, Lloyds A & C.P.

Q 111', B 11', F 30. Machy aft.



© 2020

Lloyd's Register  
Foundation

W1142-0016