

NAME OF VESSEL..... *Elmdene* .....

Extract from freeboard verification of marking form received  
from the *Hartlepool* ..... Surveyors dated the *30.11.39*

Moulded depth	<i>27</i> ft.	<i>10</i> ins.
Corresponding draught	<i>25</i> ft.	<i>0 1/4</i> ins.
Moulded depth as shewn on draught sheet	<i>27</i> ft.	<i>10 1/2</i> ins.
Tropical Freeboard	<i>2</i> ft.	<i>6 3/4</i> ins.
Summer	" <i>3</i> ft.	<i>1</i> ins.
Winter	" <i>3</i> ft.	<i>7 1/4</i> ins.
W.N.A.	" <i>✓</i> ft.	<i>✓</i> ins.
Fresh Water allowance		<i>6 3/4</i> ins.

Marked from ~~wood~~ steel upper deck.

Checked by *W.H.* .....  
Date *1.1.40* .....



© 2020

Lloyd's Register  
Foundation

*W1144 - 0005*