

Lloyd's Register of Shipping.

Fltd. 1563
56002
 JAN 17 1941

REPORT ON ANNUAL LOAD LINE SURVEY.

Name of Ship *Elmdene* Official Number *167371* Port of Registry *London*
 Place of Survey *At sea* Dates of Survey *14/1/41* Date of last Load Line Survey *2/12/39*

PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
1. Exposed on freeboard deck.			
Coamings, their stays and stiffeners...	<i>Good</i>		
Beams ...	<i>"</i>		
Fore and afters ...	<i>✓</i>		
*Covers ...	<i>Good</i>		
*Tarpaulins ... (State number per hatchway)	<i>Good (1)</i>		
*Cleats and battens ...	<i>Good</i>		
Lashings and their fittings ...	<i>"</i>		
Wedges ... (Is supply, including spares, adequate?)	<i>Good Yes</i>		
2. Exposed on superstructure decks, including raised quarter decks.			
Coamings, their stays and stiffeners ...	<i>Good</i>		
Beams ...	<i>"</i>		
Fore and afters ...	<i>✓</i>		
*Covers ...	<i>Good</i>		
*Tarpaulins ... (State number per hatchway)	<i>Good (2)</i>		
*Cleats and battens ...	<i>Good</i>		
Lashings and their fittings ...	<i>"</i>		
Wedges ... (Is supply, including spares, adequate?)	<i>Good Yes</i>		
3. Within superstructures not intact or not protected by Class I closing appliances.			
Coamings ...	<i>✓</i>		
Beams ...			
Fore and afters ...			
Covers ...			
Tarpaulins ... (State number per hatchway)			
Cleats and Battens ...			
Wedges ... (Is supply, including spares, adequate?)			



© 2020
 Lloyd's Register
 Foundation

*Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (f)).

W1144 -00222

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	Good ✓		
Closing arrangements	"		
5. To spaces below decks of superstructures which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	Good ✓		
Closing arrangements	"		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	Good ✓		
7. Within partially enclosed superstructures.			
Closing arrangements	✓		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddley openings, their covers and fastenings	Good ✓		
Skylights, their fastenings, covers and lashings	"		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	Good ✓		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	Good ✓		
11. Within partially enclosed superstructures.			
Doors and fastenings	Good ✓		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	✓		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	Good ✓		

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS.			
Forecastle	<i>Stow boards in riveted channels. Full height</i> <i>Stow boards in riveted channels. Full height</i>	} Good	
Bridge, fore end			
Bridge, after end			
Poop			
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	✓		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves	Good ✓		
17. SIDE SCUTTLES AND DEADLIGHTS			
	Good ✓		
18. GUARD RAILS			
	Good ✓		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways	✓		
20. LIFELINES (fittings and material)			
	Not Required		
21. FREEING PORTS			
Shutters	✓		
Protection bars	✓		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances	✓		
23. ITEMS NOT INCLUDED IN THE FOREGOING			
	<i>Trimming hatch & fittings. Good</i> <i>Keel tank coaming fittings. Good</i>		
24. LOAD LINE MARKS			
	Verified ✓		

[Faint, illegible text and a large diagonal line crossing the page]

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Ecard of Trade Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined. †	Signature of Surveyor.	Place.	Date.
<i>All</i>	<i>H. Cairns-Jumper</i>	<i>Hull</i>	<i>14/1/41</i>

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor *H. Cairns-Jumper* Place *Hull* Date *15/1/41*

Signature *H. Cairns-Jumper*

Date *15/1/41*

† Insert "all" in case of a complete survey.

[Handwritten signature]
 17 JAN 1941

Fee *2/4* ✓
 Number of Visits *1*

