

1

Sent to Chief Surveyors: \_\_\_\_\_

Received from Chief Surveyors: \_\_\_\_\_

VESSEL'S NAME \_\_\_\_\_

Steel S.S. "LAPWING".

Report Paisley

No 40371

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

✕ 100 A.1. (Steel) Shelter Dk. with freeboard.

1 Dk. (Steel) and Shelter Dk. (Steel W.S.).

Cell DBf 161' 238t. FPT 20t. APT 18t.

EK. 3 BH. to Shelter Dk. 1 BH to Upper Dk.

Cem. Lloyd's A. & C.P. Machinery aft.



© 2020

23. 9. 20.

Lloyd's Register  
Foundation

W1145-0025