

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *Steel S.S. JOSEPH, M. CUDAHY* Report *Pl* No. *4104***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey _____

When due _____

II 100-A-1. (Steel) Carrying petroleum in bulk
 2 Dks (Steel) & Web frames, longitudinal framing
 Cell 1B & E ~ B 59' f 41' 408t, FPT. 222t, APT 57t
 FK 16 BH (12 to upper Dk, 4 to 2nd Dk) ft Cen, A. CP, P133', B36', F40'

Nicky Aff

AD

8.3.21



© 2020

Lloyd's Register
Foundation

W1145-0114