

Tonnage Opening Fitted

Condition of

NAME OF VESSEL... S.S. "LIANASHE".....

Extract from Freeboard Verification of marking form received  
from..... Sunderland..... Surveyors dated... 16.11.36...

|  |                |                         |
|--|----------------|-------------------------|
| Moulded depth                              | 27             | ft. 8 ins.              |
| Corresponding draught                      | 25             | ft. $0\frac{1}{2}$ ins. |
| Moulded depth as shewn on<br>draught sheet | 27             | ft. 8 ins.              |
| Tropical freeboard                         | 2              | ft. $3\frac{3}{4}$ ins. |
| Summer "                                   | 2              | ft. 10 ins.             |
| Winter "                                   | 3              | ft. $4\frac{1}{4}$ ins. |
| Winter North Atlantic<br>freeboard         | -              | ft. - ins.              |
| Fresh water allowance                      | $6\frac{3}{4}$ | ins.                    |

Marked from ~~xxxx~~/steel upper deck.

Checked by.....

Date... 11.12.36...



© 2020

Lloyd's Register  
Foundation



D.O.



© 2020

Lloyd's Register  
Foundation