

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Llanashe

Rpt.

Old

New

Low

No.

31973

94262

103459

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Type of Engine

C. 4 cy. (2) 10 1/16" & (2) 20" - 13". S.R. Geared.

& L.P. Turbine D.R. Geared to screw shaft

If Boilers fitted with forced draught

Main boilers - yes
Aux boilers - no

Tail Shaft. If fitted with a continuous liner

yes

If fitted with an outside gland of

approved type

no

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + Linc. 11. 36.

S/pt.

Ymn

15.12.36

L.B. (F.D. S/pt) & 1 Adv. S.D.

JG



© 2020

Lloyd's Register
Foundation

W1147-0144