

Length

47.5

Breadth

63.3

Depth to keel

Do.

Long Bridge to top

11.01

Port of Registry

If surveyed while building, a

5c.7.28.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl S M/V "ATHEL SULTAN" Rpt. Lrk No. 19126

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1<sup>st</sup> LongTransverse No. 16583Depth "d" 22.67Framing: Table No. ✓Description Longitudinal framing as approved2<sup>nd</sup> Longitudinal No. 46432Proportions Length 13.53  
Depth =

Deck Sheerstrake

as approved

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1. (Steel). Carrying Molasses & Petroleum in Bulk  
2 D<sup>ks</sup> (Stl) + Web Frames. Longitudinal framing.  
Cell D.B. v E 83' 298t, D.T. 35' 534t, F.P.T. 219t, A.P.T. 249t  
F.K. 16 B.H. (9 B.H. to upper D<sup>k</sup>, 7 B.H. to 2<sup>nd</sup> D<sup>k</sup>) + 1cm, Rlyds ACP.  
P 119', B 34', F 48'. Machy aft.



© 2020

Lloyd's Register  
Foundation

middle line.....)

breadth and thickness at)

Forecastle Deck, Angle E or F.....

6 3