

Chief Surveyors 8.4.18

Received from Chief Surveyors

NAME

Sheelss Santore

Report

Pal

No. 2318

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

When due

7. 100 A.1. (Steel)

1 DK (Steel) & Waleframe. Longitudinal Darning.

Cell DB u E+B 58' 32" 16220 Side tanks No 1.2 & 3 P+S 19500 EP 395 ART 136

FK - 2 Intermediate Bulkheads dispensed with. 5 BH. only.

Can also P. 106' F 39'. Much abt.

N1156

-0004



© 2020

Lloyd's Register
Foundation