

1E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME *St. Margant*

Rpt. *Std. nwc. Lou* No. *31892 93907 103090*

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

of Engine *C. 4cy. (2) 10 1/4" & (2) 19" - 13" S.R. Geared.
& L.P. Lubric O.R. geared to Sc. shaft*

If Boilers fitted with forced draught *Yes*
Tail Shaft. If fitted with a continuous liner *Yes*
If fitted with an outside gland of approved type *No*

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ Luel. 8.36.*

Fitted for oil fuel 8.36 F.P. above. 150°F

Ymn
28.8.36



© 2019

Lloyd's Register Foundation
W116-0173

uous li
f the li
liner
non-co
lled at
orting
ped Sun
ie other
ie other
o,
@
lain Bil
ld
tions lo
-
pipes to t
-
elow the
al brass
osing
o or mach
orked fro
-
Pressur
Donkey
Retran
nts