

Presented to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl. S.S. "AGWIMOON" Report Phl. No. 3887**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey _____ When due _____

100 Al. (Steel) Carrying petroleum in bulk.


2 Dks. (Steel) & web frames . Longitudinal framing.

Cell DB u E & B 59' f 41' 408t. FPT 222t. APT 57t.

FK. 16 BH (12 to upper- 4 to 2nd Dk.) Pt.Cem. A & C.P.

P.133'. B.36'. F.40'. Mch. aft.

M
4. 9. 2021



Lloyd's Register
Foundation

W1166-2007