

1m, 10, 30.

Sun Shipbuilding & Dry Dock Co., Chester Pa.

Yard No 212

Report to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME ATLANTIC SUN

Report Phl.

No. 8034

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Particulars of Survey

FIRST ENTRY

When due

This is a sister vessel to the "AMERICAN SUN"

100A1 "Carrying Petroleum in bulk"

1 Dk "Electrically welded" "Longitudinal framing"

All DB, E 71' 304t, DT 23' 421t, FPT 190t, APT 109t.

FK, 16 BH, pt. Asp., Lloyd's A & CP

P 103' B 35' F 51'

Mchy Aft

O. L. 547.2'

ESD

2 $\frac{3}{8}$ "

f.c.D
14.7.41

[Signature]



© 2021

Lloyd's Register
Foundation

W1166-0126

Side Keelsons, No. each side

thickness of Intercostal Plate

Spacing